



# LUFTDYGTIGHEDSDIREKTIV

STATENS LUFTFARTSVÆSEN, Luftdygtighedskontoret (TL), Luftfartshuset,  
Box 744, Ellebjergvej 50, København SV.  
TEL 36 18 60 00, FAX 36 18 60 01, E-post: [dcaa@slv.dk](mailto:dcaa@slv.dk)  
Hjemmeside: <http://www.slv.dk>

MARS SPOL S.R.O.  
(FALDSKÆRM)  
2002-116-016(FR)R1

De i dette Luftdygtighedsdirektiv (LDD) krævede inspektioner eller modifikationer er, jf. Bestemmelser for Civil Luftfart, BL 1-1, en betingelse for, at det berørte materiel fortsat kan betragtes som luftdygtigt efter de i dette LDD angivne terminer.

## MODEL ATL-88 REDNINGSFALDSKÆRMS SERIER. ATA 25. LUFTDYGTIGHED: "RESCUE PARACHUTE - EXCLUSION FROM OPERATION."

- Berører: Som angivet under "Applicability" i nedenfor refererede AD-Note.
- Termin: Som krævet under "Compliance" i nedenfor refererede AD-Note, med mindre allerede udført.
- Aktion: Som krævet under "Compliance" i nedenfor refererede AD-Note.  
AD-Noten er bilag til og dermed en del af dette LDD.

En alternativ metode til opfyldelse af kravene i dette LDD eller en justering af terminen i dette LDD kan efter ansøgning fra ejer/operatør godkendes af Chefen for Luftdygtighedskontoret i Statens Luftfartsvæsen. Godkendelsen vil være betinget af, at en ækvivalent sikkerhed kan påvises.

Dokument: Som angivet i nedenfor refererede AD-Note.

Ikrafttrædelsesdato: Dette LDD træder i kraft ved modtagelse, dog senest 13. juni 2002

Ref. AD-Note: CAA CZ CAA-AD-T-039/2002R1 dateret 13. maj 2002

OC

Bilag: CAA CZ CAA-AD-T-039/2002R1

Dette LDD erstatter LDD 2002-116-016(FR) dateret 10. april 2002

Årsag: Udførelse af MSB No. 1/04/2002 gør Redningskærme produceret efter 30. december 1997 luftdygtige.



CIVIL AVIATION AUTHORITY  
CZECH REPUBLIC

Airport Ruzyne, 160 08 Prague 6  
Tel: 420-2-33320922, fax: 420-2-20562270

**Airworthiness  
Directive**

**Number: CAA-AD-T-039/2002R1**

Date of issue: 13. maj 2002

**MARS SPOL S.R.O.**

ATL-88, ATL-88/92-S, ATL-88/90

**APPLIANCE -RESCUE PARACHUTE - EXCLUSION FROM OPERATION**

**Applicability:** Rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90, produced by MarS spol s.r.o. after December 30, 1997, on which Mandatory Service Bulletin No.: 1/04/2002 has not been accomplished.

**Reason:** Since December 30, 1997 producer MarS spol s.r.o. has not a valid Approval Certificate for Production according to § 17 of Czech Aviation Act and producer continued in production and release to service after this date without Approval Certificate. From this reason all rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90 produced after December 30, 1997 are unairworthy for operation in civil aviation.

Since May 7, 2002 producer MarS a.s. has Approval Certificate for maintenance for rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90. After accomplishing of Mandatory Service Bulletin No.: 1/04/2002, with result "Airworthy", are above mentioned rescue parachutes airworthy for operation in civil aviation.

**Effective date:** Upon receipt.

**Compliance:** Upon receipt of this AD hand over (after agreement with MarS a.s.) all rescue parachutes ATL-88, ATL-88/92-S, ATL-88/90 produced by MarS spol s.r.o. (now MarS a.s., Okružní II. c.p. 239, 569 43 Jevicko, Czech Republic, Phone: +420 462 327 816, Fax: +420 462 327 837) after December 30, 1997 for inspection and for accomplishing of Mandatory Service Bulletin No.: 1/04/2002.

*Remarks: Where applicable the requirements of this AD must be integrated into Aircraft Technical Documentation. Address inquiries concerning this AD to: Civil Aviation Authority, Airworthiness Division, Ruzyne Airport. 160 08 Prague 6. Czech Republic, tel: 420 2 33320922 . fax: 420 2 20562270.*