

DANMARK GRØNLAND OG FÆRØERNE

**AIC B
27/08**



AIM/Aeronautical Information Management
Ellebjergervej 50
DK-2450 Copenhagen SV
Denmark
TEL: +45 36 18 60 00, FAX: +45 36 18 60 22
E-mail: ais@slv.dk, Internet: www.slv.dk

10 APR 2008

AIC B 27/08. EUR RVSM Post-Implementation Height Monitoring Requirements

(Replaces AIC B 57/02)

Minimum Monitoring Requirements and Height Monitoring Procedures

All operators which operate in the airspace where RVSM is applied are required to participate in the ongoing monitoring programme. On the official website of the EUROCONTROL Navigation Domain a table shows the minimum monitoring requirements. Operators are requested to ensure that the required number of aircraft are monitored to comply with the minimum monitoring requirements over a 2 year period. New operators, or operators with new aircraft, should attempt to comply with the minimum monitoring requirements as soon as possible.

For further information on "Height Monitoring Procedures" and "Minimum Monitoring Requirements" see

<http://www.ecacnav.com/content.asp?PageID=65>

(TO)